

CRISP RUTHIE TAPESTRY LOOM PARTS LIST 45" and 60"

1. 2 Castle Posts
2. 2 Cross Bars
3. 8 Wedges
4. 1 Warp Beam with nylon webbing and 5/8" roundsteel tie on rods
5. 1 Cloth Beam " " " " " " " " " "
6. 4 Pawls with bolts and nuts
7. 4 Beam holder blocks
8. 4 Allen head 1/2" bolts
9. 2 Harnesses
10. 2 1/8" Steel harness supports
11. 4 Steel push rods
12. 1 Rocker bar
13. 6 Tie up rods - 1/4" steel threaded each end (2 for 45")
14. 6 Foot treadles (2 for 45")
15. 3 Foot treadle spacer blocks (1 for 45")
16. 1 Treadle bar with 3 12" rods to hold treadles (1 rod for 45").
17. 1 Reed holder/beater assembly
18. 1 Counter weight assembly
19. 2 Counter weight assembly roller bearings
20. 2 Counter weight assembly stop blocks with 4 #121 screws
21. 2 3/8" Shoulder bolts with nuts
22. 1 Heddle tying jig

Tools needed for assembly

- 2 Allen wrenches 3/16", 3/8" Included with loom
- Screwdriver
- Phillips head screwdriver
- 1/2" Crescent wrench
- Small hammer or mallet